




A T E X EXPLOSION PROOF ELECTRIC CHAIN HOISTS



- 1 - Supply current/pneumatic air
- 2 - Pressure monitoring
- 3 - Cable connection Ex

 SWISS QUALITY

DUSTPROOF EXECUTION	GASPROOF EXECUTION
<p> II 3D Ex tc IIIA T130 °C Db</p> <p><i>Equipment group II</i> <i>Equipment category 3</i> <i>Zone 22 (D)</i> <i>Temperature =<130 °C</i></p> <ul style="list-style-type: none"> ▪ IP 65 ▪ Temperature monitoring ¹ ▪ Geared limit switch ▪ Cable connections Ex 	<p> II 3D Ex tc IIIA T130 °C Db II 3G Ex pz IIA T3 Gb</p> <p><i>Equipment group II</i> <i>Equipment category 3</i> <i>Zone 2 (G) 22 (D)</i> <i>Temperature class T3</i></p> <ul style="list-style-type: none"> ▪ IP 65 ▪ Temperature monitoring ¹ ▪ Geared limit switch ▪ Cable connections Ex ▪ Overpressure monitoring ² (required air pressure, connection plugged ø 6 mm)

¹ Safety: Main and creep speed of the electric chain hoist are separately supervised.

² Safety: In case of a pressure drop within the hoist casing the operating voltage is interrupted immediately.